

MR3287-12

Serial No. 10/773,399

Response to Office Action dated 4 August 2004

Please replace the ABSTRACT, page 8, with the following amended

ABSTRACT:

### ABSTRACT OF THE DISCLOSURE

A screw including a head, a shank under the head in a whole body, and a thread helically built upon the outside trunk of the shank; wherein, said The thread ~~projected projects~~ from the circular trunk of the shank and is consisted consists of an upper flight flank, a low flight flank, and an peak edge on the joint line of the upper and low flights flanks, and an even number of axial slots formed on the thread. ~~The feature is that every~~ Every axial slot is beveled with a back angle to form a ~~sheared section~~ tilt surface from the upper flight flank to the low flight flank to form a cutting edge for facilitating to rapid fastening with a smaller tapping torque as tapping in.

BEST AVAILABLE COPY

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**